




**SWA – Halling, Kent - Treatment works**



**TWA – 5 sites - Chemical storage tank bunds**



**SWA – Twyford WTW bund coating**



**Deutschbank London – Diesel storage tank coating - internal**





**TWA – Cleeve – WTW – bund**



**(Concrete condition after surface preparation)**



**(Repairs in progress)**



**(Chemical resistant coating applied)**

**CHEMICAL BUND COATINGS PROFILE**  
SWA Ashford WWTW – Repair & coating to Sludge Tank




**(Surface after preparation – pore holes)**



**(Repairs to concrete surface)**



**(Epoxy fillet & coating to tank support legs)**



**(First coat applied - Grey)**



**(De-nibbing first coat)**



**(Second coat applied – Red)**

**TWA – Hornsey WTW – Chemical coating to sulphuric acid bund**